

### **AMENDMENTS TO THE SPECIFICATION**

Please amend the specification as follows:

Please replace the paragraph beginning at page 7, line 13 (paragraph [0045] of the published application) with the following rewritten paragraph:

FIG. 4 further illustrates a technique for mounting docking station 12 to a crash cart 61 or other structure. Top surface 44 includes three mounting holes 48. Structure 82 is not a mounting hole, but rather is a feature related to operation of front clamp 40. A fastener such as a screw 84 is inserted into a mounting hole, which is large enough to accommodate the head of screw 84. The head of screw 84 therefore does not seat against top surface 44. Mounting holes (not shown in FIG. 4) on the bottom side of base 18 may be aligned with mounting holes 48, but the mounting holes in the base are not large enough to accommodate the head of screw 84. When screw 84 is driven into a crash cart 61 or other structure with a screwdriver 86, the head of screw 84 seats against the inner surface of base 18, thereby mounting docking station 12 to the crash cart 61 or other structure.